

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS		ATTN J KAST EMP 8077-8832		#39	
JHM		4633		DATE RECEIVED		DATE OPENED		DATE CODE	
11/29/90		12/21/90		AT-3-B8		7649569		7649569	
ACCESSORIES		MAGNODS		SCOPE BASE				ORDER	
								R 90-31832	

FROM:

FLANSBURG, SCOTT
MAIN STREET
POLAND NY 13431

SHIP TO:

FLANSBURG, SCOTT
MAIN STREET
POLAND NY 13431

13431

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA	DOOR
----------------	--------------------	--------------------------------	------------	------------	-----------	-----	------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST "Fired when took safe off, twice, when it was cold"

MAIN FAULT Trigger assembly rusted from unknown source Internal trigger parts not moving freely.

PARTS Replace trigger assembly at no-charge as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE