Hor	482-6362	EST EST	Rest FIMATE		styne, TX	2		
Name_	DANNY FI	letcher		Due Kloc . 1	2, 1980	·	_	
Addres	1/ 1/6		******	-	·			
City	VAN ABIY	ne 74xas		Phone				
	Insurance Co.				Adjuster 3			
	AME & MODEL SERIAL NO. PU (Serv)				LICENSE NO. MILEAGE			
BER	DESCRI	MOIT	LABOR	SUBLET	MATERIALS	Pr	ARTS	
	Po-wate to un	losseed sout	.4	19500				
1	Der PANET.	Shell	70			65	119	
VZ	terior PANE		.5			59	7 64	
V 7	inted Side Il	Indow .	2.0			189	200	
1	Paint Misc		2.8		77.50			
						1		
		-				1		
	*** · · · · · ·					1 -		
						1		
						+-		
_			1			1		
				-		 		
-, -			1			\vdash		
			 		······································	1-		
			1			+		
-+-		-	- 			+		
			1	——————————————————————————————————————		-		
		·	- r - 202 - 2 - 1			+		
						ــــــــــــــــــــــــــــــــــــــ		
URED PAY	\$ 5 INS CO	PAYS	. R O No	LABOR		234	00	
NS. CHECK PAYABLE TO				SUBLET		195	00	
ie above Iditional r	is an estimate, based parts or labor which m	on our inspection, a	ind does not cover i	MATERIALS		د17	30	
xenea uc). Occasionaliv attei	work has started	WARD broken or i	PARTS		213	36	
ımaged p	parts are discovered wo on parts and labor are	thich are not evident	on first inspection.	WRECKER				
	•				$-\Box$			
	- 1	1		TAX		1		
	1)//	K	1	SUB TOTAL		735	86	
MADE BY				TOTA	LOF	735	86	
ORIZATION	FOR REPAIR You are hereby	authorized to make the abo	ve specified reports to the co	or described become				