

INITIAL L.M.	CUSTOMER ORDER NO.		ATTN DENNIS SANITA			
DATE RECEIVED 01/20/93	DATE OPENED 01/20/93	DATE CODE LG 2-86	SERIAL NUMBER B6772566	NEW SERIAL NUMBER	MODEL AND GRADE 700 243 RDL	
ACCESSORIES W/STUDS						

FROM:

GOULD, LEONARD G
126 COOLIDGE AVE
LEHIGH ACRES

FL 33936

SHIP TO:

GOULD, LEONARD G
126 COOLIDGE AVE
LEHIGH ACRES

FL 33936

CUST NO: 073742 C-D.DL

ACCOUNT NUMBER	ACCOUNT NUMBER/VIC 059015	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	------------------------------	--------------------------------	------------	------------	-----------	------------

GUN CONDITION ☒ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED							REPAIR CHARGE
							EXCISE
							TAX
							INSURANCE
							UPS
							PARCEL POST
							TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP					E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5	D2		E4	F4
WOOD						F5
METAL			C2			

MAINT FAULT
 Purchased new 11/92
 Trigger pull 4 1/2 lbs, scrubbed .015, both within spec
 front sight ramp worn, stock cracked at rear of trigger guard.
 Left msg 2/86 Unable to duplicate Customer's Concern.
 Trigger pull 4 1/2 lbs, scrubbed .015, both within spec
 front sight ramp worn, stock cracked at rear of trigger guard.

PARTS Return in new box Send owners manual	COMMENTS	REMARKS	CLEAN	TEST	TARGET	PATTER
	1/24/93 discussed findings with customer via phone agreed to fit new trigger assembly to gun, both parts in mfg. fit new, stock new and replace front sight ramp. no further work. 1/24/93 discussed findings with customer via phone agreed to fit new trigger assembly to gun, both parts in mfg. fit new, stock new and replace front sight ramp. no further work.		☒	☒		
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1