

RECEIVING AND ESTIMATING REPORT

FROM

THE GUN CORRAL
2827 EAST COLLEGE AVENUE
DECATUR, GA 30030
404-299-0288

SHIP TO:

ORDER
R 91-19

YOUR ORDER NO.

DATE REC'D.

TERMS

SHIP VIA

7197

WARRANTY

UPS

CONTENTS-MERCHANDISE-
POSTMASTER:
IF NOT DELIVERED IN 15 DAYS
RETURN TO SENDER.

OUR ORDER NO.

177497 B

09-25-91

DATE SHIPPED

INVOICE TO:

REMINGTON ARMS COMPANY, INC.,
ARMS SERVICE DIVISION
14 HOMER AVENUE
ILION, NY 13357

SHIP TO:

GUN CORRAL, THE
2827 E COLLEGE AVE.
TWIN OAKS SHOP CTR.
DECATUR GA
USA 30030

FROM DATE

ESTIMATED

VIA

UPS

QUANTITY

MODEL

DESCRIPTION

WARRANTY REPAIR STATION

UNIT PRICE

TOTAL

1

700

30-06 SN-B6890053 EC-BH

We are sending you this gun on behalf of our customer S. Stroud. The complaint is that the gun is going off while on safety or while being pushed off to fire. We worked on this gun on 10-25-90 (our #5440) in which we found the gun very dirty and greasy with the only problems being a bind in the cocking piece and rough threads in the firing pin mech. Our customer is very afraid of this gun and wants it inspected and completely tested (it has AD's three times total. Please repair as needed under WARRANTY and return to us as soon as possible. THANK YOU!!

Thian

5

PARCEL POST

TOTAL

WORN

☐ MISUSED☐ MARRED

or while being pushed off

However, it was noted the
not and safety force is too low
assembly is not with
assembly is not with
assembly is not with

PARTS

Offer new trigger assembly at
original cost, as a gesture of
will, based on condition of
assembly

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTER

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 R