

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER R 94-11039	
INITIAL FJB	CUSTOMER ORDER NO. 008496						
DATE RECEIVED 03/28/94	DATE OPENED 03/28/94	DATE CODE LS 2-69	SERIAL NUMBER 221537	NEW SERIAL NUMBER	MODEL AND GRADE 706 30-06	BDL	
ACCESSORIES W/STUDS		SCOPE BASE					
FROM: KELLY, OWEN RR 1 BOX 254 ESPERANCE NY 12066				SHIP TO: KELLY, OWEN RR 1 BOX 254 ESPERANCE NY 12066			
ACCOUNT NUMBER		ACCOUNT NUMBERING 059015		CUST NO: 094902 C.D.D.		FROM DATE	
GUN CONDITION		WRITE ☐		ESTIMATED 5-12-94		VIA DOOR	
☐ NEW ☒ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED		<i>* some rust pits on M.</i>		REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL			
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	<i>Failed when safety was released</i>					
TRIGGER GROUP		B2			E1	F1	
BOLT ASSY.		B3			E2	F2	
BARREL ASSY.		B4		D1	E3	F3	
REC. ASSY.		B5		D2	E4	F4	
WOOD			C1	D3	E5	F5	
METAL			C2				
MAIN FAULT <i>May 2-69 Unable to duplicate customer's concern as noted. Could find no fault trigger and safety functioned normally in every respect. Took trigger apart, still nothing wrong. Replaced trigger assy it is change as g. got one of good unit and to restore customers confidence in RFL.</i>							
PARTS	COMMENTS <i>Trigger pull measured 3 to 3 1/2 lbs as reqd. and now off was .0105</i>						
REPAIRMAN <i>RBS</i>	PROOF	CLEAN	TEST	TARGET	PATTERN		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE		