

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-01032

CUSTOMER ORDER NO

CALL TAG A
W/BTM PARTFRED MARTIN
SCOPE MNTS.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

11/07/94

01/10/94

OY 7-74

6764989

700

7MM MAG

ADL

ACCESSORIES

W/STDS

SCOPE BASE

FROM:

KOLESZARIK, STEVEN
975 SUMMIT DRIVE
WINDBER

PA 15

SHIP TO:

KOLESZARIK, STEVEN
975 SUMMIT DRIVE
WINDBER

PA

15963

CUST NO: 40 C.O.D L

ACCOUNT NUMBER

ACCOUNT NUMBER W/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Trigger Assy Dirty - Internal components sticky At Times -
 Brown Residue Visible In Assy On Components - Assy Has
 Been Adjusted Outside Factory - No Sealant On Front Mount
 Screws - Several Indentations On Side Of Housing

PARTS

COMMENTS

Replace Trig Assy As A Gesture Of
 Good Will - Test - Return To
 Customer

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OF COPY

RD6925 REV 1/92