

RECEIVING AND ESTIMATING REPORT							
COMMENTS							
ATT SANITA/W RUBBER PAD							
INITIAL	CUSTOMER ORDER NO.						
02							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	BDL		ORDER
02/09/89	02/24/89	OX 7-73	4655885	700 30-06	BDL		R 89-07231
ACCESSORIES W/STUDS							
FROM:				SHIP TO:			
LOFTIN & TAYLOR 2619 MAIN ST JACKSONVILLE FL 32206				LOFTIN & TAYLOR 2619 MAIN ST JACKSONVILLE FL 32206			
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		WRITE	FROM DATE	ESTIMATED	VIA
							UPS
DEAR CUSTOMER: WE ARE RIGHT IN THE MIDDLE OF OUR MOST BUSY TIME OF THE YEAR IN SERVICING GUN RETURNS FROM ACROSS THE USA AND CANADA. IF OUR REPAIR TURNAROUND TIME IS A BIT LONGER THAN USUAL, IT IS BECAUSE WE WILL NEVER CUT CORNERS JUST TO RUSH THE GUN BACK TO YOU. WE ALWAYS STRIVE TO GIVE YOU A QUALITY REPAIR IN COMBINATION WITH AS TIMELY A GUN RETURN AS POSSIBLE. SO PLEASE BEAR WITH US AND THANK YOU FOR YOUR SUPPORT.							
REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL		
GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED							
CUSTOMER'S REQUEST							
MAIN FAULT							
PARTS							
REPAIRMAN							
PROOF							
CLEAN							
TEST							
TARGET							
PATTERN							
GALLERY TESTER							
DATE							
DATE							
DATE							
DATE							
DATE							
DATE							
OFFICE COPY							

TP 5 1/2
54.009

RD4925 REV. 6/88