# RECEIVING AND ESTIMATING REPORT

COMMENTS

| INITIAL | CUSTOMER ORDER NO. |
|---|---|
| "B" | |

| DATE RECEIVED | DATE OPENED | DATE CODE | SERIAL NUMBER | MODEL AND GRADE | | ORDER |
|---|---|---|---|---|---|---|
| 01/10/89 | 01/19/89 | EU 10-71 | 6486895 | 700 30-06 | ADL | R 89-02461 |

ACCESSORIES SCOPE BASE

FROM:
MASHBURN ARMS CO INC. (PRO)
1218 PENN AVE.
OKLAHOMA CITY, OK 000073107

SHIP TO:
MASHBURN ARMS CO INC. (PRO)
1218 PENN AVE.
OKLAHOMA CITY, OK
000073107

| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE ☐ | PROM. DATE | ESTIMATED | VIA |
|---|---|---|---|---|---|
| | | | | | UPS |

DEAR CUSTOMER:
WE ARE RIGHT IN THE MIDDLE OF OUR MOST BUSY TIME OF THE YEAR IN SERVICING GUN RETURNS FROM ACROSS THE USA AND CANADA. IF OUR REPAIR TURNAROUND TIME IS A BIT LONGER THAN USUAL, IT IS BECAUSE WE WILL NEVER CUT CORNERS JUST TO RUSH THE GUN BACK TO YOU. WE ALWAYS STRIVE TO GIVE YOU A QUALITY REPAIR IN COMBINATION WITH AS TIMELY A GUN RETURN AS POSSIBLE. SO PLEASE BEAR WITH US AND THANK YOU FOR YOUR SUPPORT.

| REPAIR CHARGE | TAX | INSURANCE | UPS | PARCEL POST | TOTAL |
|---|---|---|---|---|---|
| | | | | | |

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

MAIN FAULT

PARTS

| REPAIRMAN | PROOF | CLEAN | TEST | TARGET | PATTERN |
|---|---|---|---|---|---|
| GALLERY TESTER | DATE | DATE | DATE | DATE | DATE |

RO6925 REV. 6/88

OFFICE COPY