

RECEIVING AND ESTIMATING REPORT

COMMENTS

To Product Service

ORDER

R93-25771

CUSTOMER ORDER NO.

RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

19/93

12/02/93

CT 4-70

6327164

700 243 WIN

ADL

SSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

A:

MCBRIDES GUN SHOP

C/O NBS

2915 SAN GABRIEL/30TH N LAMAR.

AUSTIN

TX 78705

SHIP TO:

MCBRIDES GUN SHOP

C/O NBS

2915 SAN GABRIEL/30TH N LAMAR

AUSTIN

TX

78705

CUST NO:006578 WILM

JUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

CONDITION

EW

IGHTLY WORN

VORN

ERY WORN

INREPAIRABLE

VARRED

REPAIR CHARGE

25.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

LE

A1

B1

GER GROUP

B2

E1

F1

F ASSY.

B3

E2

F2

REL ASSY.

B4

E3

F3

ASSY.

B5

E4

F4

D

C1

D2

E5

F5

AL

C2

FAULT

*Upon receipt bolt stop release and trigger not functioning. Trigger & bolt
 heavily covered with grime, sticky substance. Trigger adjustment screw has
 been loosened without the package. Replied 1/19/90*

S

COMMENTS

*trigger pull - 4 1/2 lbs.
 trigger lift - .007*

*Replaced complete trigger assembly
 & other action at 1/2 normal
 replacement cost as per order of good
 unit*

Go ahead

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92