

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-09351

INITIAL
F.P.S.

CUSTOMER ORDER NO.

X.C.F. Supply

DATE RECEIVED
03/11/94

DATE OPENED
03/14/94

DATE CODE
DM 9-92

SERIAL NUMBER
B7533586

NEW SERIAL NUMBER

MODEL AND GRADE
XP100 7MM BR

ACCESSORIES

SOFT CASE

FROM:

MEL'S TRADING POST
105 S BROWN
RHINELANDER

WI 54501

SHIP TO:

MEL'S TRADING POST
105 S BROWN
RHINELANDER

WI
54501

CUSTOMER NO: 009044 WILM L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059001

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☒ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

Fires when closing bolt

RIGGER GROUP

B2

E1

F1

OLT ASSY.

B3

E2

F2

ARREL ASSY.

B4

D1

E3

F3

EC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

ETAL

C2

IN FAULT

After 9-92 unable to duplicate customer concern as rec'd. However, after inspection and re-assembly firing pin would follow down. Replate trigger and check clearances for assy with counter balance, stock and trigger guard. Trigger does not have proper shape and tip of trigger interferes with trigger guard causing malfunction.

RTS

COMMENTS

Trigger pull 2 1/2 lbs as rec'd

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94