

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-16490

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED
05/23/94

DATE OPENED
05/23/94

DATE CODE
DE 9-84

SERIAL NUMBER
B6630223

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

FROM:

MUTARELLI, MICHAEL
835 HICKORY ROAD
WALNUTPORT

PA 18088

SHIP TO:

MUTARELLI, MICHAEL
835 HICKORY ROAD
WALNUTPORT

PA 18088

CUST NO: 097690 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3				F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

*Light mag. 1984 Upper mag. not duplicate to customer
owner. Inspection revealed that the upper mag. was not
properly assembled and caused a heavy loading of the
upper mag. which caused the upper mag. to be damaged.
The inspection also revealed that the upper mag. was not
properly assembled.*

PARTS

COMMENTS

*Upper mag. not duplicate to customer
owner. Inspection revealed that the upper mag. was not
properly assembled and caused a heavy loading of the
upper mag. which caused the upper mag. to be damaged.
The inspection also revealed that the upper mag. was not
properly assembled.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
TAL					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

*to H/S
5/25/94*