

## RECEIVING AND ESTIMATING REPORT ✓

|                                   |                         |                             |                           |                                   |  |                   |  |
|-----------------------------------|-------------------------|-----------------------------|---------------------------|-----------------------------------|--|-------------------|--|
| INITIAL<br>JJM                    |                         | CUSTOMER ORDER NO.<br>30733 |                           | COMMENTS                          |  |                   |  |
| DATE RECEIVED<br>01/17/91         | DATE OPENED<br>01/25/91 | DATE CODE<br>EJ 10-89       | SERIAL NUMBER<br>C6448728 | MODEL AND GRADE<br>700 270 BDL/LH |  | ORDER<br>R 91-026 |  |
| ACCESSORIES<br>W/STUDS SCOPE BASE |                         |                             |                           |                                   |  |                   |  |

FROM:

NAGEL'S GUN SHOP  
6201 SAN PEDRO AVE.  
SAN ANTONIO TX 78216

SHIP TO:

NAGEL'S GUN SHOP  
6201 SAN PEDRO AVE.  
SAN ANTONIO TX 78216

|                |                    |                                |            |            |           |            |
|----------------|--------------------|--------------------------------|------------|------------|-----------|------------|
| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> | CLEAN/TEST | PROM. DATE | ESTIMATED | VIA<br>UPS |
|----------------|--------------------|--------------------------------|------------|------------|-----------|------------|

|               |     |           |     |             |       |
|---------------|-----|-----------|-----|-------------|-------|
| REPAIR CHARGE | TAX | INSURANCE | UPS | PARCEL POST | TOTAL |
|---------------|-----|-----------|-----|-------------|-------|

GUN CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☒ MISUSED☐ MARRED

CUSTOMER'S REQUEST

1) Sometimes goes off when safety is taken off  
2) Sometimes very hard to take safety off.

MAIN FAULT

Trigger assembly rusted from unknown source, trigger parts not moving freely, not as designed

PARTS

Replace trigger assembly at no charge as gesture of good-will.

|                  |       |       |      |        |         |
|------------------|-------|-------|------|--------|---------|
| REPAIRMAN<br>BZF | PROOF | CLEAN | TEST | TARGET | PATTERN |
| GALLERY TESTER   | DATE  | DATE  | DATE | DATE   | DATE    |

OFFICE COPY

RD6925 REV 7/9