

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660
GENERAL CONDITION: GOOD R #: 013305
OUTSIDE WORK: SCOPE MOUNTED, CEMENT ON DATE: 6-21-72
TRIGGER ETC. DOES NOT LOOK LIKE DUPONT, FROM: N.Y. CITY POLICE DEPT.
FIRED AMMO TYPE: - BRONX, N.Y.
& CONDITION: _____ GUN #: 125445
PROOF: R.E.P. INSP.: 95 TEST: 13 CODE: ER = 10/68
HEADING: O.K. GK./CAL.: 223
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: 20 ROUNDS APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR BROKEN, SEAR & CONNECTOR ENGAGEMENT
CORNERS BROKEN OFF, BROKEN PIECE OF CONNECTOR
SOLDERED TO TRIGGER, CONSIDERABLE RUST ETC. ON
TRIGGER & IN HOUSING. CEMENT ON SCREWS DOES NOT
HAVE THE SAME APPEARANCE AS DUPONT, USED EXCESSIVELY,
COMPLAINT: FIRE ON CLOSING.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE CUSTOMER PROBABLY EXPERIENCED PIERCED
PRIMERS WHICH BROUGHT ABOUT THE CORNER BREAKING
OFF AND THE BROKEN CONNECTOR