RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL	CUSTOMER ORDER NO.
"B"	F99476

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE			ORDER
01/31/89	02/17/89	LX 2-73	6617486	700	30-06	BDL	R 89-06236

ACCESSORIES: W/STUDS

FROM:
NORCKAUER ASSOC. (SR)
10220 FLORIDA BLVD.
BATON ROUGE LA 70815-0000

SHIP TO:
NORCKAUER ASSOC. (SR)
10220 FLORIDA BLVD.
BATON ROUGE, LA
70815-0000

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS

DEAR CUSTOMER:
WE ARE RIGHT IN THE MIDDLE OF OUR MOST BUSY TIME OF THE YEAR IN SERVICING GUN RETURNS FROM ACROSS THE USA AND CANADA. IF OUR REPAIR TURNAROUND TIME IS A BIT LONGER THAN USUAL, IT IS BECAUSE WE WILL NEVER CUT CORNERS JUST TO RUSH THE GUN BACK TO YOU. WE ALWAYS STRIVE TO GIVE YOU A QUALITY REPAIR IN COMBINATION WITH AS TIMELY A GUN RETURN AS POSSIBLE. SO PLEASE BEAR WITH US AND THANK YOU FOR YOUR SUPPORT.

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

MAIN FAULT

PARTS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RDW23 REV. 4/88

OFFICE COPY