

RECEIVING AND ESTIMATING REPORT							
INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS W/1 STUD ONLY			
DATE RECEIVED 10/17/89	DATE OPENED 01/28/89	DATE CODE BU 1-71	SERIAL NUMBER 6392261	MODEL AND GRADE 600 243	MOHAWK	ORDER R 89-03896	
ACCESSORIES SCOPE BASE		L/REAR SIGHT					
FROM: JAMES R. PERRIGO Z MALONE PLUMBING & HEATING ELM STREET RD. MALONE, N.Y. 12953				SHIP TO: JAMES R. PERRIGO Z MALONE PLUMBING & HEATING ELM STREET RD. MALONE, N.Y. 12953			
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>		PROM. DATE	ESTIMATED	VIA UPS	
<p>DEAR CUSTOMER: WE ARE RIGHT IN THE MIDDLE OF OUR MOST BUSY TIME OF THE YEAR IN SERVICING GUN RETURNS FROM ACROSS THE USA AND CANADA. IF OUR REPAIR TURNAROUND TIME IS A BIT LONGER THAN USUAL, IT IS BECAUSE WE WILL NEVER CUT CORNERS JUST TO RUSH THE GUN BACK TO YOU. WE ALWAYS STRIVE TO GIVE YOU A QUALITY REPAIR IN COMBINATION WITH AS TIMELY A GUN RETURN AS POSSIBLE. SO PLEASE BEAR WITH US AND THANK YOU FOR YOUR SUPPORT.</p>							
REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL		
<p>GUN CONDITION: <input type="checkbox"/> NEW <input type="checkbox"/> SLIGHTLY WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> MISUSED <input type="checkbox"/> MARRED</p> <p>CUSTOMER'S REQUEST</p>							
MAIN FAULT							
PARTS							
<p><i>Begin Part - 5.20</i> <i>End Part - 0115</i></p>							
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE		
OFFICE COPY							