

RECEIVING AND ESTIMATING REPORT						ORDER R 94-13497	
INITIAL TAL	CUSTOMER ORDER NO.					COMMENTS	
DATE RECEIVED 04/18/94	DATE OPENED 04/19/94	DATE CODE CZ 04-75	SERIAL NUMBER 6856453	NEW SERIAL NUMBER	MODEL AND GRADE 700 25-06 BDL		
ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS							
FROM: RENO, JAY A. 2323 FOURTH STREET SANTA ROSA CA 95404				SHIP TO: RENO, JAY A. 2323 FOURTH STREET SANTA ROSA CA 95404			
CUST NO 98187 C.O.D.							
ACCOUNT NUMBER	ACCOUNT NUMBER NC	WRITE ☐	FROM DATE	ESTIMATED	VIA UPS		
GUN CONDITION						REPAIR CHARGE 10.00	
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED						EXCISE TAX INSURANCE UPS PARCEL POST TOTAL	
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	B1					
TRIGGER GROUP		B2			E1	F1	
BOLT ASSY.		B3					
BARREL ASSY.		B4		D1	E3	F3	
REC. ASSY.		B5		D2	E4	F4	
WOOD			C1	D3	E5	F5	
METAL			C2				
MAIN FAULT Upon receipt, we could not duplicate Western Union. Shot assembly has been given better effort to duplicate shot. Has not been received in your for proper charging. Apparently, the unit that all 3 trigger adjustment were done then it was set. The trigger assembly was replaced.							
PARTS			COMMENTS				
#26345 Trigger Assembly			Trigger pull measured 2 3/4 to 3 1/2 lbs as tested and left was .0085				
			Further complete trigger assembly and then action at 1/2 normal adjustment both in pattern of good work				
			Good work				
REPAIRMAN			PROOF	CLEAN	TEST	TARGET	PATTERN
TAL							
GALBY TESTER			DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6825 REV. 1/94

to A/S 5/19/94