RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN: D SANITA

INITIAL	CUSTOMER ORDER NO.
RLP	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
09/28/89	10/03/89		A6511590	700 7MM MAG/BDL/LH	R 89-23508

ACCESSORIES: L/ REAR SIGHT EO 10-77 XQ3 12-78

FROM:
JOE ROSS
RD #2
BOX 216
DUNBAR PA 15431

SHIP TO:
JOE ROSS
RD #2
BOX 216
DUNBAR PA
15431

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

MAIN FAULT

PARTS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88

OFFICE COPY

PRINTED BY THE STANFORD REGISTER COMPANY, U.S.A. STANFORD