

Customer Complaint.

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL.
GENERAL CONDITION: GOOD R #: 27632
OUTSIDE WORK: STOCK BEDDING ALTERED. DATE: 12-3-70
SCOPE MOUNTED. FROM: R. ROYSE
FIRED AMMO TYPE: - PORTLAND, OREGON.
& CONDITION: _____ GUN #: 6275235
PROOF: R.E.P. INSP.: 9 ASSEMBLER 90 TEST: 55 CODE: ES = 10/69
HEADING: O.K. GA./CAL.: 7MM REV. MAG.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: POOR GROUPS, FIRED WHEN SAFETY WAS PUSHED
TO FIRE POSITION.

INCIDENT: BARREL BORE ROUGH, FOLLOWED DOWN.

COMMENTS: THE FOLLOW DOWN CAN NOT BE DUPLICATED.
BARREL BORE EXCESSIVELY ROUGH - SHOULD BE
REPLACED.