

RECEIVING AND ESTIMATING REPORT

M93-17685

INITIAL	CUSTOMER ORDER NO.	W/PACHMAYR RECOIL PAD			
FPS	DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER
	08/20/93	08/25/93	84	B6626691	
ACCESSORIES	SCOPE		BASE		
MODEL AND GRADE		700 270 WIN ADL			

FROM:	SHIP TO:
SATIN SEAR PISTOLSMITH 424A PECAN DR. ALEDO TX 76008	SATIN SEAR PISTOLSMITH 424A PECAN DR. ALEDO TX 76008

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	CUST NO: 082651 C.O.D	PROM. DATE	ESTIMATED	VIA
				9-9-93	UPS

GUN CONDITION	REPAIR CHARGE
☐ NEW	EXCISE
☐ LIGHTLY WORN	TAX
☐ WORN	INSURANCE
☐ VERY WORN	UPS
☐ UNREPAIRABLE	PARCEL POST
☐ MARRED	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL						

MAIN FAULT: Unable to disassemble without damage. However, disassembly revealed that all 3 adjustment screws have had the correct amount, indicating they have been tampered with without the proper knowledge of how to properly adjust them. In a word, they are bad. All in all, the gun is a good one.

COMMENTS: Repaired trigger assembly at 16 mm adjustment and in operation of gun well. Go ahead.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	P
C.C.					
GALLERY TESTER	DATE	DATE	DATE	DATE	D

OFFICE COPY

RD6925