

RECEIVING AND ESTIMATING REPORT						COMMENTS		ORDER R 92-09812	
INITIAL JJM	CUSTOMER ORDER NO.								
DATE RECEIVED 04/06/92	DATE OPENED 04/13/92	DATE CODE QV 7-79	SERIAL NUMBER A6791557	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	BDL			
ACCESSORIES		W/STUDS		SCOPE BASE					
		L/REAR SIGHT							
FROM: ST LAURENT, DAVID 585 KEELING RD NORTH POLE AK 99705					SHIP TO: ST LAURENT, DAVID 585 KEELING RD NORTH POLE AK 99705				
CUST NO: 060810 C.D.D.									
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS			
GUN CONDITION						REPAIR CHARGE			
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED						☐ EXCISE ☐ TAX ☐ INSURANCE ☐ UPS ☐ PARCEL POST ☐ TOTAL			
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT			
CYCLE	A1	B1							
TRIGGER GROUP		B2	<i>Discharged twice when safe was pushed off</i>						
BOLT ASSY.		B3			E2				
BARREL ASSY.		B4			E3				
REC. ASSY.		B5		D1	E4				
WOOD			C1	D2	E5				
METAL			C2	D3					
MAIN FAULT <i>Cannot duplicate Complaint - Trigger assembly and safe operate properly. Disassembly of safe showed trigger assembly. When bolted outside of factory to trigger pull adjustment has changed (safety released) trigger pull below spec. measure at 3 pounds.</i>									
<i>Trigger pull 3 pounds; over-let 1009"</i>									
PARTS	COMMENTS			<i>Offer to re-adjust present assembly to specification. If we can install a new trigger assembly at a normal cost as a gesture of good-will if that will better restore confidence in the rifle.</i>					
REPAIRMAN			PROOF	CLEAN	TEST	TARGET	PATTERN		
GALLERY TESTER			DATE	DATE	DATE	DATE	DATE		