

RECEIVING AND ESTIMATING REPORT

INITIAL **BARBER - Kinzer PPS GAL RE0005064** AG ATTN: JACK KAST *Set up time Copy F. Supny* **R** ORDER 94-13738

DATE RECEIVED **07/20/94** DATE OPENED **04/21/94** DATE CODE **ES 10-69** SERIAL NUMBER **6284774** NEW SERIAL NUMBER MODEL AND GRADE **700 7MM MAG BDL**

ACCESSORIES **W/STUDS L/SIGHTS**

FROM:

SHIP TO:

THOMASIAN, JACK
14119 BADE DR.
HARREN

MI 48093

THOMASIAN, JACK
14119 BADE DR.
HARREN

MI 48093

CUST NO: 096333 C.L.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C 059015	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION					REPAIR CHARGE
☐ NEW ☒ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED					EXCISE
					TAX
					INSURANCE
					UPS
					PARCEL POST
					TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE						
RIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Gun mfgn 10/69 Unable to duplicate customer concern as rec'd. Inside of trigger housing had grease like lubricant on side plates and trigger very gummy. Otherwise very well maintained. Replaced trigger Assy at N/C as gesture of good will and to restore customer confidence

RTS	COMMENTS <i>Trigger pull measured 5+0.5 1/2 LBS as rec'd. sear lift was .0105</i>					
	<i>4/21/94</i>					
	<i>*ALSO Grease in trig. Housing/Rec. recent Look's Like R 109</i>					
	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

FD6925 REV. 1/94

BARBER - Kinzer PPS GAL RE0005064

PPS 05059