

RECEIVING AND ESTIMATING REPORT

ORDER NO.			COMMENTS		
			J CUSTOM SHOP POTTER		
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
7/08/88	07/18/88	WH 8-87	B6785345	700 280 KS LH	R 88-19645
SOURCES W7STUDS					

TO:	SHIP TO:
JOHN A. VELASCO 259 EL PORTAL WAY SAN JOSE, CA. 95119	JOHN A. VELASCO 259 EL PORTAL WAY SAN JOSE, CA. 95119

UNIT NUMBER	FROM DATE	ESTIMATED	VIA
			UPS
CHARGE	TAX ST	INSURANCE	UPS
	TAX CITY	PARCEL POST	TOTAL
			\$

CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE

OWNER'S COMPLAINT - see letter - Rem warranty gunsmith did following:
 - small chip out of stock near trig guard;
 - small scratch on bottom of bolt 3" from forend
 - small black spots on bolt sewing; Guard screws
 - stock & screws damaged by screw driver
 - also alleged FSR (Bolt stop not working
 - ~~AIRED TARP 6UN~~ Taken to J. Hutton first

FAULT

DEMERT CODE

Disposition 7/20/88 RHP	
① If found justified (I did) repair all new cosmetic defects n/c. If want to	
***** THE "TARP" MASTER CHARGE, use TARP ch.#	
② Per instructions from J. Hutton, replace trig assy at n/c. ③ Ship, prepaid, ASAP do above customer -	
COMPUTER REF. ONLY	PROOF
	(CLEAN) (TEST) (TARGET)
	REPAIRMAN

RD6925 REV. 3/86