

Vollman

Pure Plaster found broken in TA
between housing & arm cover

This piece could be piece of plaster used when gluing holding plate

Options

1. re-assemble & test using repaired TA
2. get new TA & test