

To Fred Suppl

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER 94-14433	
INITIAL FPS	CUSTOMER ORDER NO.			CALL TAG ATTN: DENNIS SANITA W/BTM. PART OF SEE THRU SCOPE MNTS			
DATE RECEIVED 04/27/94	DATE OPENED 04/28/94	DATE CODE DV 9-79	SERIAL NUMBER A6813397	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	BDL	
ACCESSORIES W/STUDS							
FROM: VOLPE, STEPHEN R. 1017 GREEN GLEN DRIVE DEBOIS PA 15801				SHIP TO: VOLPE, STEPHEN R. 1017 GREEN GLEN DRIVE DEBOIS PA 15801			
CUST NO: 096641 G.L.O.D.							
ACCOUNT NUMBER	ACCOUNT NUMBER NC	WRITE ☐	PROM. DATE	ESTIMATED	VIA	UPS	
GUN CONDITION			REPAIR CHARGE			20.00	
☐ NEW			EXCISE				
☒ LIGHTLY WORN			TAX				
☐ WORN			INSURANCE				
☐ VERY WORN			UPS				
☐ UNREPAIRABLE			PARCEL POST				
☐ MARRED			TOTAL				
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	B1					
TRIGGER GROUP		B2					
BOLT ASSY.		B3					
BARREL ASSY.		B5					
REC. ASSY.							
WOOD			C1	D3	E5	F5	
METAL			C2				
MAIN FAULT <i>Upon receipt we could not duplicate customer concern. Bolt stop switching changed, explanation revealed that the action is correct with gun slightly out of time. Bottom of trigger assembly and main trigger housing covered with dirt. Rifle has been properly maintained. Trigger pull measured 2 1/2 lbs.</i>							
PARTS	COMMENTS <i>Replace compact trigger assembly & manufacture at 1/2 normal cost as part of good will Go ahead</i>						
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE		

OFFICE COPY