

GUN# B30 W | SCOPE
SERIAL # 71001302
CAL- 30.06 SPRG.

REMINGTON M710 DAT PHASE II
DAILY TEST DATA SHEET

TRACKING # TLW0010
PROJECT #241095

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-	
				RDS. FIRED	TOTAL RDS.
JW/ SW	9/9/00	HEADSPACE	MIN. + .002		
JW/ SW	9/9/00	PROOF, HEADSPACE	PROOF, INSPECT, HEADSPACE MIN. + .003 + PROOF STAMP	1	1
JA/BL/TC	9-9-00	Trigger Pulls			
JA/BL/TC	9-9-00	Sear/Trigger Engagement / Sear L:RT			
TC	9-9-00	Inspects			
JW/ SW	9-10-00	SAAMI DROP TEST	JAR OFF, DROP, ROTATION		
JA/BL/JW	9-11-00	Trigger Pull/Engagement	SAAMI Drop (See TLW 0010AR)		
JA/BL/SW	9-11-00	Inspection	No Cracks		
MRT	9-11-00	MAGNAFLUX BUT HEAD - NO INDICATIONS			
		EXTENDED JAR OFF	6" - 18" - 24" - Plastic Insert Cracked on Barrel Horizontal, Right Side of Stock up - stopped test on 48"		
JW/ SW	9-14-00		Replace plastic insert #1302-2		
JW/ SW	9-14-00	AVERAGE TRIGGER PULL	4.458 ENGAGEMENT, 0230		
JW/ SW	9-14-00	EXTENDED JAR OFF	Finished 48" / INSPECTED		
JW/ SW	9-14-00	TRIGGER PULL / ENGAGEMENT AFTER EXTENDED JAR OFF			
	9-15-00	EXTENDED DROP TEST	PLASTIC INSERT BROKE ON 72" EXTENDED DROP TEST ON BARREL HORIZONTAL / LEFT SIDE OF STOCK UP - SCOPE BROKE ON BARREL VERTICAL, MUZZLE UP		
JW/ SW	9-26-00		REPLACED SCOPE		
JW/ SW	9-28-00		REPLACED PLASTIC INSERT		
JW/ SW	9-28-00		SET TRIGGER PULL ENGAGEMENT AFTER REPLACE INSERT		
JW/ SW	9-28-00	EXTENDED DROP TEST	BROKE PLASTIC INSERT ON 72" EXTENDED DROP TEST ON BARREL HORIZONTAL, BOTTOM OF STOCK UP		
JW/ SW	9-28-00		REPLACED PLASTIC INSERT		
JW/ SW	9-28-00	TRIGGER PULL/ENGAGEMENT SET TO SPEC. AFTER REPLACING INSERT			
JW/ SW	9-28-00	EXTENDED DROP TEST	CONTINUED TEST @ 72" - COMPLETE		
JW/ SW	9-28-00	Inspection	Scope bent, Bolt handle bent		
JW/ SW	9-29-00	Extended Rotation Test	Complete		
JA/ BL	10-2-00	Trigger Pull	average 3.875		
JA/ BL	10-2-00	Engagement	102620		

THIS SHEET IS TO ACCOMPANY THE FIREARM AT ALL TIMES THROUGHOUT TESTING

Forms

BARBER - 5.22.06/0003118