

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO.		DATE CODE		SERIAL NUMBER		MODEL AND GRADE		ORDER	
08/89	12/12/89	12/12/89	06254208	700	30-06	ADL	R	89-30554	
DATE OPENED		DATE CODE		SERIAL NUMBER		MODEL AND GRADE		ORDER	
08/89		12/12/89		06254208		700 30-06 ADL		R 89-30554	
W/STHDS									
SHIP TO:					SHIP TO:				
JIMMY WILSON RT 2 BOX 436 PENNINGTON GAP VA 24277					JIMMY WILSON RT 2 BOX 436 PENNINGTON GAP VA 24277				
NT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐		PROM. DATE	ESTIMATED	VIA			
					12-20-89	UPS			
CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL				
CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED									
USER'S REQUEST: <i>Gun fires when you release safety</i>									
ULT: <i>Trigger assembly and rear guard screw rusted from unknown source</i>									
1) Replace trigger assembly and rear guard screw at N/C as per customer request - will be replaced per phone call to customer 1/12/90									
2) Charge \$10.00 handling and return shipping fee 1/12/90									
REPAIRMAN: <i>WBC</i> PROOF: CLEAN: TEST: TARGET: PATTERN:									
GALLERY TESTER: DATE: DATE: DATE: DATE: DATE: DATE:									

RD4925 REV. 6/88

OFFICE COPY