

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-24860

INITIAL JJM	CUSTOMER ORDER NO.					
DATE RECEIVED 11/13/92	DATE OPENED 11/19/92	DATE CODE AV 3-79	SERIAL NUMBER A6728733	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MMAG	BDL
ACCESSORIES W/STUDS		SCOPE BASE				

FROM:

CLASSIC GUNS & COLLECTIBLES
1868 MT MEIGS RD
MONTGOMERY AL 36107

SHIP TO:

CLASSIC GUNS & COLLECTIBLE
1868 MT MEIGS RD
MONTGOMERY AL 36107

CUST NO: 070422 C.O.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION <input type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED						REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	<i>"When getting unloading the rifle, i.e. removing a shell from the chamber, or placing a shell in the chamber and closing the bolt, the rifle has spontaneously discharged".</i>					
BOLT ASSY.						
BARREL ASSY.						
REC. ASSY.	B5		D2	E4	F4	
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Could not duplicate complaint. Rifle operates normally. However, disassembly of rifle revealed much dirt & rust on under side of barrel, recoil buffer, receiver and trigger assembly - needs good cleaning.*

Trigger pull 4 1/2 Pounds; rear lift .007"

PARTS	COMMENTS
	<i>Rifle needs good cleaning on bottom of barrel - action</i>
	<i>Offer following options:</i>
	<i>1) To clean rifle & return with present T.A.</i>
	<i>2) To clean rifle & replace trigger assembly at normal cost, as a gesture of good will if that will better return confidence in the rifle</i>
REPAIRMAN	PROOF
GALLERY TESTER	DATE
CLEAN	DATE
TEST	DATE
TARGET	DATE
PATTERN	DATE

OFFICE COPY

RD6925 REV. 1/8