

BARBER - Kinzer PPS GAL RE 0013413

Remington Arms Co., Inc.

Product Service

Legal Case #:5111

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
210518	11/16/2010	11/17/2010	11/17/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Cabelas		Cabelas	2424 Hwy 6&50	Grand Junction	CO	81505		W 970-683-5000

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

11/22/20 Per dealer's note with firearm, rifle has fired on safety release.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 WIN MA	85599	D6638848	CE	4/21/2010 10:28:53 AM

Date Purchased	Where Purchased	Accessories	Original Owner
	CABELA S INC/WAREHOUSE /	SCOPE AND RING BASES,TRIGGER LOCK	U

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, clean, test at no charge under warranty						

Repair/Replacement Cost	Repair/Replacement Date
27.00	11/22/2010

11/22/10 Per Ilion, could not duplicate concern, check over, clean, and test fire no charge under warranty.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		F.SUPRY
	Exam Date		11/17/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	HAD TO CUT OFF THE TRIGGER LOCK TO REMOVE, WILL REPLACE WITH A NEW ONE.
Barrel	Description		26" 300 WIN MAG
	Date Code		CE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

BARBER - Kinzer PPS GAL RE 0013414			
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	SOME LITE RUSTING ON BBL
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A (SCOPED)
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		SCOPE AND RING BASES, TRIGGER LOCK

Firearms Reacquire or Repair Form For Firearms Department Only

Customer Name: Christopher Robert Kirsch 5111 26⁴
CE 4/10
y[#]
Address 1979 Hwy 145
City: Telluride State: CO. Zip code: 81435
Phone Number: 970 729-2130 County: San Miguel
Drivers License or Other ID: 98-280-0878
Customer's Signature: [Signature]

Firearm Make: Remington Model: 700 SPS
Action Type: Bolt Caliber or Gauge: 300 Win Mag
Serial Number: D6638848


Purchased at: Cabela's #33
Original Tracing ID: 1797074
Date of Original Purchase: 8/29/2010 Trans: 1965 Reg: 100

For POS USE ONLY: Return SKU# _____
() Repair for customer : firearm does not go through POS
() Reacquire as used gun using original SKU _____
(X) Reacquire as defective gun using original SKU 03028-313

Customer was issued a refund for: Dollar Amount 549.99

Note Defect or Service Needed: Gun fires when safety is taking off.

Send Back to Remington
could not duplicate concern.
check over completely, CLEAN +
Best fire. WARRANTY

Serial Number: **D6638848**
Model: **700**

RE00210518

New Gun ID#	<u>23176135 / 2019717</u>
37 Screen Done	<u>Book / 187 ga 11-9-10</u>
Date	
Hardcopy Done	
Date	

2200 BARBER - Kinzer PPS GAL RE 0013415

7925

Cabela's Retail Inc., Grand Junction, CO (970)683-5000

Dock Shipment Form

Associate Name BRENT 14Date 11-09-2010

Customer # _____

Customer Name CHRIS CABELAS #33

Mailing Address _____

City _____

State _____

Zip Code _____

Home Phone 970-683-5000

Contact Phone _____

E-mail Address _____

Shipping Address (If different):

Recipient's Name REMINGTON ARMO INC COShipping Address 14 HOFFER AVECity LIONState NYZip Code 13357Ship to Phone 315-895-3200

Contact Phone _____

POS Date _____

Tran _____

Reg _____

List Only Items Shipped

Quantity	UPC/SKU	Description	Price	Extended Price
1	03176135	REMINGTON 700 SPS 300 win mag		
		2019717		
		D6638848		

Address 1979 Hwy 145 Tride NoContact # 970 729 2130Manufacturer RemingtonModel modk 700Caliber/Gauge 300 mag

Serial # _____

% Charged _____

Merchandise Total _____

Oversize fee _____

Shipping/Handling _____

Taxes _____

Total Order _____

Shop cabelas.com/gunlibraryName Chris KIRSCH

frmRepairMain - FGI Repairs

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System

frmREInquiry - Repair Inquiry

Repair Number: **RE00210518** Serial: D6638848 Model 700 Center Fire Caliber 300 Repairman: Bruce Travis
 WIN MAG Produced: 04/21/2010 SKU: 85639 Status: Repairing 11/17/2010 8:12:28 AM

Verify Repair

ADDRESS INFORMATION

Customer ☒ Received from **Return To** ☒ Received from

Name: CABELAS RETAIL INC CABELAS INC.
 Address 1: 115 CABELA DRIVE 2424 HWY 6&50
 Address 2: PO Box PO Box
 City: SYDNEY GRAND JUNCTION
 State: NE Zip Code: 69162 Country: US CO Zip Code: 81505 Country: US

FFL: 5 84 077 01 3D 03147 042013

Contact / Condition Problems Estimate History / Status Shipping / Billing

Date	Code	User ID	Desc1	Desc2
11/15/2010 10...	New	lopatafl	Repair Added	
11/17/2010 7...	Maint	Travisbw	Repair Maintenance	Status: Rep
11/17/2010 8...	Estimate	Travisbw	Estimate Update	Status: Rep
11/17/2010 8...	Expedite	penceril	From: Repair Bench	To: Gallery

Shipping Hold ☐ Interface Hold ☐ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ Return as Received ☐ Has Been Approved ☐ Internal Repair ☐ Exclude TATC ☐

Current Status: Repairing
 11/17/2010 8:12:28 AM
 Travisbw
 Gallery
 Repair Location
 ILN
 Current Location
 ILN
 Transfer Number

Repair Search Refresh Close

frmREI frmREI frmREI frmREI

naglet ILN/Prod frmRepairMain NAGLET Wednesday, Nov 17 2010 8:31 AM

start 12 Mi frmRep... 9 Micr 2 Inte... Part Se... DMS Stock O... XM201... 9:11 AM

RECEIVED
 NOV 18 2010

BY:

