

RIFLE # A-3
S.N. 71163365
CAL. 30 - 06 SPRG

M / 710 EXTRUDED RECEIVER D.A.T.

PROJECT: #
TLW: # 1530

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-	
				RDS. FIRED	TOTAL RDS.
B.Lee	7-12-04	Initial Headspace	min +.004	TLW1530B	
B.Lee	7-13-04	Proof	OK	TLW1530C	1
B.Lee	7-13-04	Re-measure Headspace	min +.004	TLW1530D	
B.Lee	7-13-04	Endents	.028 .019 .020 Avg. .019	TLW1530E	
SW	7-14-04	Engagement	See data sheet	TLW1530F	
SW	7-15-04	Sear/Firing Pin Head Engagement	See data sheet	TLW1530G	
SW	7-15-04	Trigger Pull	See data sheet	TLW1530H	
BL	7-15-04	Safety on/off forces	See data sheet	TLW1530I	
BL	7-15-04	Bolt opening/closing forces	See data sheet	TLW1530J	
SW	7-16-04	Sear Lift	See data sheet	TLW1530F	
BL	8-5-04	modified basic Jack Function Test	mag box fell apart at 27 Rds	TLW1530N	80
JS	8-10-04	(Modified Receiver)	Machined chamber to aid in feeding	TLW1530N	120
BL	8-12-04	modified basic Jack Function Test	0 Malfunctions	TLW1530O	20
SW/JS	8/13/04	Shoulder Function Test	OK	TLW1530O	20
BL/JS	8/13/04	Accuracy	OK	TLW1530O	20
SW	8/16/04	Clean + Inspect	OK Headspace Min +.004	TLW1530R	500
JS	8/24/04	Endurance	FTX/	TLW1530Q	741
SW	8/30/04	Clean + Inspect	OK Headspace Min +.005	TLW1530R	
BL	8-31-04	Magazine Release Latch	Broken at 840 Rds / Replaced		
BL	8-31-04	Endurance	malfunctions 1671 Rds	500	1241
SW/BL	9/1/04	Clean + Inspect	OK Headspace Min +.005	TLW1530R	
BL	9/2/04	Endurance	GETEJECT 7 FTX/	TLW1530Q	500
SW/BL	9/2/04	Clean + Inspect	OK Headspace Min +.005	TLW1530R	
BL	9-8-04	Endurance	5 FTX/	TLW1530Q	500
SW/BL	9/8/04	Clean + Inspect	OK Headspace Min +.005	TLW1530R	

DAILY DATA SHEET

Remington Arms Confidential

Page 1

BARBER - 5.22.06 R005768

Confidential - BARBER - 5.22.06 R005768 Order

Williams V. Remington

ET22768