

5-15-79

1. A 6759969 (6)

1. Cracked at reinforcement screw bridge ✓
2. Bolt handle hits front of clearance cut
3. washer under floor plate screws

2. A-6759278 (7)

1. Cracked at reinforcement screw bridge ✓
2. Cracked back sides of groove
3. washers under floor plate screws

3. A6763954 (3)

1. Bolt handle hits clearance cut
2. washer under floor plate screws.

4. A 6759270 (8)

1. Crack left side of groove ✓
2. Crack at reinforcement screw bridge
3. washer under floor plate screw

5. A 6759297 (5)

1. Cracked at reinforcement screw bridge ✓
2. Bolt handle hits clearance cut
3. Crack left side of groove
4. washer under floor plate screws

6. A-6762473 (4)

1. Crack at reinforcement screw bridge ✓
2. Back sides of groove
3. Rear of front vertical section

7- H 4759482 (2)

1. crack at reinforcement seen bridge
2. washer under floor plate seen

8. A6759269 (1)

1. cracked at reinforcement seen bridge
2. left side belt groove
3. Cracked belt groove front magazine box cut
of rivet at shaft, rivet
5. washer under floor plate seen

9. A6759386

OK

↓ SANDS

10- A6760141

1. washer, under front floor plate seen

11 A6760420

12 - A6760076

1. Nick in Belt handle clearance cut

3. A6763919

1. washer under front floor plate seen

14 - A6760723 - OK

15 - A6763401 - - NICK IN floor plate cut

16 - A6760400 - washers under front floor plate seen