

PACKAGING PHOTOS

A-8

Muzzle broke
through the
Packing Carton.

