


VISUAL INSPECTION

A-22

Knot in Checkering



Lack of Stain
under Finish.

