

Rev. 2-15-61

P.I. YES GUN EXAMINATION REPORT NUMBER: 37 MODEL: 700 BDL L4.
 GENERAL CONDITION: SLIGHTLY WORN R #: 28088
 OUTSIDE WORK: SCOPE MOUNTED DATE: 11-22-82
 FIRED AMMO TYPE: UNKNOWN FROM: CAMPBELL LAND CO.
905 Town & Country Bldg.
Suite 350
Houston, TX 77024
 & CONDITION: _____ GUN #: 6859417
 PROOF: R.E.P. 2 INSP.: 123 TEST: 63 CODE: 5-76
 HEADING: O.K. GA./CAL.: .270 WIN.
 BREACH OPENING: O.K. CHECKED BY: SAW
 RECOIL SHOULDERS: O.K. APPROVED: SAW 12/28/82
 CHAMBER: O.K. APPROVED: SAW 12/28/82
 TEST: _____ APPROVED: SAW 12/28/82
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: SAW 12-28-82

COMPLAINT: "... Rifle Fired When I was Trying To Unload It..."

INCIDENT: Moved The Safety To The OFF Position To Open The Bolt.

COMMENTS: Replace fire control as requested by customer.