

Rev. 2-15-61

P.I. NO GUN EXAMINATION REPORT NUMBER: 566 MODEL: 700 ADL
 GENERAL CONDITION: FAIR R #: 28511
 OUTSIDE WORK: SCOPE MOUNT, S/STUDS, & RECOIL DATE: 12-9-81
PAD ADDED - R/SIGHT MISSING TECH: CHET PAULSON, INC
935 FAWCETT AVE
TACOMA WASH
 FIRE ARM TYPE: NOT KNOWN GUN #: 6280500
 & CONDITION: _____ CODE: ES-10-69
 PROCP: B DISP.: 88 TEST: 87 CL./CAL.: 3006
 FEADING: OK CHECKED BY: M. HARDY
 BREACH OPENING: OK APPROVED: 92/12/10/81
 RECOIL SHOULDERS: OK APPROVED: RG 12/10/81
 CHAMBER: OK APPROVED: WOB 12-10-81
 TEST: _____ APPROVED: PM 12-10-81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 12-10-81
BRIGHT METAL SCRATCHES ON REC. STOCK
PITTED TIE CHIPPED

COMPLAINT: FIRES WHEN SAFETY IS RELEASED

INCIDENT: _____

COMMENTS:

Trigger pull 4# - unable to duplicate
customer complaint.

Replace fire control - no charge

Make sure safety doesn't hit wood.