

Rev. 2-15-61

P.I. NO GUN EXAMINATION REPORT NUMBER: 566 MODEL: 700 ADL
 GENERAL CONDITION: FAIR R #: 28511
 OUTSIDE WORK: SCOPE MOUNT, S/STOCKS, & RECOIL DATE: 12-9-81
PAD ADDED - R/SIGHT MISSING FROM: CHET PAULSON, INC.
935 FAWCETT AVE.
TACOMA WASH
 FIRE ARM TYPE: NOT KNOWN GUN #: 6280500
 & CONDITION: _____ CODE: ES-10-69
 PROCP: B INSP.: 88 TEST: 87 GA./CAL.: 3006
 READING: OK CHECKED BY: M. HARDY
 BREACH OPENING: OK APPROVED: JAN 12/10/81
 RECOIL SHOULDERS: OK APPROVED: PE 12/10/81
 CHAMBER: OK APPROVED: NWB 12-10-81
 TEST: _____ APPROVED: PH 12-10-81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

BRIGHT METAL SCRATCHES ON REC. STOCK
PITTED THE CHIPED

COMPLAINT: FIRES WHEN SAFETY IS RELEASED

INCIDENT: _____

COMMENTS:

Trigger Pull 4# - Unable to duplicate
customer complaint.

Replace fire control - No charge

Make sure safety doesn't hit wood.