

P Ma GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL

GENERAL CONDITION: Good R# : 07215

OUTSIDE WORK: SCOPE MOUNTED DATE: 4-23-71

FIRED AMMO TYPE: - ORD. NEBRASKA

CONDITION: _____ GUN #: 6320412

PROOF: R.E.P.B INSP.: 9 TEST: 49 CODE: AT-3/70

HEADING: O.K. GA./CAL.: 270

BREACH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O. K. APPROVED: _____

CHAMBER: O.K. [] [] [] APPROVED:

TEST: TEN ROUNDS APPROVED:

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN OR DAMAGED COMPONENTS. SLIGHT BURR

ROUND EJECTOR HOLE.

COMPLAINT: LOADING SHELL INTO BARREL IT WENT OFF ALSO

UNABLE TO EXTRACT SHELL.

INCIDENT:	EXHIBIT
-----------	---------

COMMENTS: UNABLE TO DUPLICATE FIRES ON CLOSING. IN TEST

EJECTOR STUCK BACK CAUSING FAILURE TO EJECT.

EJECTOR WAS FREED UP AND BURR REMOVED AFTER

WHICH RIFLE FUNCTIONED O.K.

**PLAINTIFF'S
EXHIBIT**

3275