Figure 5 contains pictures of the Model 710 bolt lugs before and after the first. Only a slight amount of wear can be seen between the before and after pictures.





Figure 5. 710 bolt lugs, before test (left) and after 5000 rounds (right).



Subject to Protective Order - Williams v. Remington