CONFIDENTIAL

Remington Arms Company India Research & Development Technical, Center 315 West Ring Road Elizabethtown, KY 42701

2.1 TEST SUMMARY TABLE

The following Table lists the individual test procedures that were completed during the DAT series and the Final Status of each by individual category. Note: Final Status is listed as "Passed", "Acceptable", "For Information" or "...Did Not Meet Specifications"

Passed = those characteristics for which a specification or criteria was required to be met.

Acceptable = those for which specific criteria have not been clearly established.

For Information = those characteristics without specific criteria and which were taken to provide data to establish expected product design levels.

Did Not Meet Specifications = those characteristics for which criteria or specifications were established but not met by the submitted sample.

| TEST PROCEDURE | Phase I | PHASEΠ | tender Fraidtender Fraidtender |
|--|-----------|--------------|--|
| | | DAT 1. DAT 2 | ************************************** |
| | | OR POST-DAT | |
| | | Status | |
| 3.1 INITIAL INSPECTIONS, TESTS & MEASUREMENTS | | | |
| 3.1.1 Headspace & Proof Testing | | | |
| 3.1.1.1 TLW0010A – Measure Headspace | Completed | Completed | Passed |
| 3.1.1.2 TLW0010B - Proof Test | Completed | Completed | Passed |
| 3.1.1.3 TLW0010C - Re-Massure Headspace Proof Test | Completed | Completed | Passed |
| 3.1.2 Forces | | | |
| 3.1.2.1 TLW0010D – Firmg Pin Indent | Completed | Completed | Did not meet |
| | | | S.A.A.M.1. |
| | | | Specifications |
| 3.1.2.2 TLW0010E – Sear/Frigger Engagement & Sear Lift | Completed | Completed | Did not meet all |
| | | | Specifications |

San.2001 Design Acceptance Test Remington M/710 Centerfire Rifle;
R & D Technical Center Project No. 241039; TLW 0100
file: EATest Reports \ Firearms Tests \ M710_DAT_REPORT_JAN01_Rev1.doc

Page 9

CONFIDENTIAL

REV. 1 - 0824/66 0:5943